

PRC Environmental Management, Inc. 233 North Michigan Avenue Suite 1621 Chicago, IL 60601 312-856-8700 Fax 312-938-0118



PRELIMINARY ASSESSMENT/ VISUAL SITE INSPECTION

METAL FINISHING RESEARCH CORPORATION CHICAGO, ILLINOIS ILD 045 700 945

FINAL REPORT

Prepared for

U.S. ENVIRONMENTAL PROTECTION AGENCY Office of Waste Programs Enforcement Washington, DC 20460

 Work Assignment No.
 : C05087

 EPA Region
 : 5

 Site No.
 : ILD 045 700 945

 Date Prepared
 : March 11, 1993

Date Prepared : March 11, 1993
Contract No. : 68-W9-0006
PRC No. : 009-C05087IL7S
Prepared by : PRC Environment

repared by : PRC Environmental Management, Inc.

Contractor Project Manager : (Michael G. Duffin)
Shin Ahn

Telephone No. : (312) 856-8700
EPA Work Assignment Manager : Kevin Pierard
Telephone No. : (312) 886-4448


TABLE OF CONTENTS

<u>Sectio</u>	<u>n</u> .			<i>.</i>										Page	2
EXEC	CUTIVE	SUMM	IARY	• . • • • • • • •						 •••			•	ES-1	
1.0	INTR	ODUCT	ION							 				1	
2.0	FACI	LITY D	ESCRIPTION .							 				4	ļ
	2.1 2.2 2.3 2.4 2.5 2.6	FACII WAST HISTO REGU	LITY LOCATIO LITY OPERATI E GENERATIO DRY OF DOCUI ULATORY HIST RONMENTAL S	ONS ON AND . MENTED ORY	MANA MELI	GEMI EASES	ENT	• • •	• • • •	 	• • •			4 6 . 10)
		2.6.1 2.6.2 2.6.3 2.6.4	Climate Flood Plain and Geology and Scround Water	d Surface oils	Water					 	 	• •		. 12 . 12	
	2.7	RECE	PTORS		• • • • •		• • • •			 				. 13	,
3.0	SOLII	WAST.	E MANAGEMI	ENT UNI	TS				• • • •	 				. 15	
4.0	AREA	S OF C	ONCERN	• • • • • •						 				. 18	
5.0	CONC	CLUSIO	NS AND RECO	MMEND	ATION	ıs				 	• • •			. 19	ı
REFE	RENCE	ES								 				. 22	
<u>Attacl</u>	nment	:										-			
Α	EPA I	PRELIM	INARY ASSESS	SMENT F	FORM	2070- 1	12								
В	VISUA	AL SITE	INSPECTION	SUMMA	RY AN	ID PH	ото	GRA	PHS						
С	VISUA	AL SITE	INSPECTION	FIELD N	OTES										

LIST OF TABLES

<u>Table</u>	<u>Page</u>
1	SOLID WASTE MANAGEMENT UNITS 7
2	SOLID WASTES 9
3	SWMU SUMMARY
	LIST OF FIGURES
<u>Figure</u>	<u>Page</u>
1	FACILITY LOCATION
2	FACILITY LAYOUT 8

PELEASED
DATE 18:16-14
RIN & 22 16-14
INITIALS EXECUTIVE SUMMARY



PRC Environmental Management, Inc. (PRC), performed a preliminary assessment and visual site inspection (PA/VSI) to identify and assess the existence and likelihood of releases from the solid waste management units (SWMU) at the Metal Finishing Research Corporation (MFRC) facility in Chicago, Cook County, Illinois. This summary highlights the results of the PA/VSI and the potential for releases of hazardous wastes or hazardous constituents from the SWMUs identified. In addition, a completed U.S. Environmental Protection Agency (EPA) Preliminary Assessment Form (EPA Form 2070-12) is included in Attachment A to assist in prioritizing RCRA facilities for corrective action.

The MFRC facility manufactures liquid and powdered proprietary chemical blends used by the metal industry for heat treating and finishing. The facility generates and manages the following waste streams: nonhazardous rinse water and wastewater treatment system (WWTS) sludge (D007). The facility formerly blended alkaline powders containing cyanide salts. The facility also formerly treated rinse waters to remove cyanide. The operations that generated these cyanide-containing rinse waters were discontinued in May 1992.

MFRC has been the sole owner and operator of the facility since its construction in 1962. The facility occupies 1.2 acres in a mixed-use area and employs 13 people. In 1989, the office and warehouse buildings were constructed in an area owned by MFRC. MFRC had been leasing the property to an adjacent business who used the area for parking. MFRC is a wholly-owned subsidiary of the Heatbath Corporation. The facility is currently regulated as a hazardous waste treatment, storage, or disposal (TSD) facility. On September 28, 1988, MFRC applied for a Part A permit withdrawal. The request was denied by the Illinois Environment Protection Agency (IEPA). MFRC is currently preparing a closure plan for the Hazardous Waste Storage Area (SWMU 2). On November 8, 1992, IEPA revoked the facility's interim status; however, MFRC is still regulated as a TSD pending closure of the Hazardous Waste Storage Area (SWMU 2).

The PA/VSI identified the following two SWMUs at the facility:

Solid Waste Management Units

- 1. Wastewater Treatment System (WWTS)
- 2. Hazardous Waste Storage Area

No areas of concern were identified during the PA/VSI.

ENFORCEMENT CONFIDENTIAL

All wastes generated at the facility are managed indoors. Process wastewater is contained in a tile-lined drainage system. All concrete floors are epoxy sealed. MFRC does not store substances that contain solvents or volatile organic compounds (VOC) during its operations. The facility is located in an urbanized area that is mostly paved. Facility SWMUs have a low potential for release to ground water, surface water, air, and on-site soils.

The MFRC facility is located in a mixed-use area within 0.1 mile of residences. Facility access is controlled by locked doors and a 24-hour security alarm system.

The nearest surface water body, South Fork of the Chicago River, is 1.3 miles northwest of the facility. The South Fork of the Chicago River is used for industrial purposes and leads to the Chicago Sanitary and Ship Canal, which flows southwest and is also used for industrial purposes.

Ground water is not used as a drinking water source in the area. Sensitive environments are not located on site. The nearest sensitive environment is an open water area in Sherman Park located 2.0 miles southwest of the facility. The facility has had no documented releases to the environment.

PRC recommends no further action at this time.

1.0 INTRODUCTION

PRC Environmental Management, Inc. (PRC), received Work Assignment No. C05087 from the U.S. Environmental Protection Agency (EPA) under Contract No. 68-W9-0006 (TES 9) to conduct preliminary assessments (PA) and visual site inspections (VSI) of hazardous waste treatment and storage facilities in Region 5.

As part of the EPA Region 5 Environmental Priorities Initiative, the RCRA and CERCLA programs are working together to identify and address RCRA facilities that have a high priority for corrective action using applicable RCRA and CERCLA authorities. The PA/VSI is the first step in the process of prioritizing facilities for corrective action. Through the PA/VSI process, enough information is obtained to characterize a facility's actual or potential releases to the environment from solid waste management units (SWMU) and areas of concern (AOC).

A SWMU is defined as any discernible unit at a RCRA facility in which solid wastes have been placed and from which hazardous constituents might migrate, regardless of whether the unit was intended to manage solid or hazardous waste.

The SWMU definition includes the following:

- RCRA-regulated units, such as container storage areas, tanks, surface impoundments, waste piles, land treatment units, landfills, incinerators, and underground injection wells
- Closed and abandoned units
- Recycling units, wastewater treatment units, and other units that EPA has usually exempted from standards applicable to hazardous waste management units
- Areas contaminated by routine and systematic releases of wastes or hazardous constituents. Such areas might include a wood preservative drippage area, a loading or unloading area, or an area where solvent used to wash large parts has continually dripped onto soils.

An AOC is defined as any area where a release of hazardous waste or constituents to the environment has occurred or is suspected to have occurred on a nonroutine and nonsystematic basis. This includes any area where a strong possibility exists that such a release might occur in the future.

The purpose of the PA is as follows:

- Identify SWMUs and AOCs at the facility
- Obtain information on the operational history of the facility
- Obtain information on releases from any units at the facility
- Identify data gaps and other informational needs to be filled during the VSI

The PA generally includes review of all relevant documents and files located at state offices and at the EPA Region 5 office in Chicago.

The purpose of the VSI is as follows:

- Identify SWMUs and AOCs not discovered during the PA
- Identify releases not discovered during the PA
- Provide a specific description of the environmental setting
- Provide information on release pathways and the potential for releases to each medium
- Confirm information obtained during the PA regarding operations, SWMUs, AOCs, and releases

The VSI includes interviewing appropriate facility staff; inspecting the entire facility to identify all SWMUs and AOCs; photographing all visible SWMUs; identifying evidence of releases; making a preliminary selection of potential sampling parameters and locations, if needed; and obtaining additional information necessary to complete the PA/VSI report.

This report documents the results of a PA/VSI of the Metal Finishing Research Corporation (MFRC) facility (EPA Identification No. ILD 045 700 945) in Chicago, Cook County, Illinois. The PA was completed on January 6, 1993. PRC gathered and reviewed information from the Illinois Environmental Protection Agency (IEPA), National Oceanic and Atmospheric Administration (NOAA), Illinois State Geological Survey (ISGS), U.S. Geological Survey (USGS), U.S. Department of Commerce (USDC), Federal Emergency Management Agency (FEMA), Gale Research Company, Chicago Department of Planning and Development, Metropolitan Water Reclamation District of Greater Chicago (MWRDGC), and from EPA Region 5 RCRA files. The VSI was conducted on January 14, 1993. It included interviews with facility

representatives and a walk-through inspection of the facility. PRC identified two SWMUs and no AOCs at the facility.

PRC completed EPA Form 2070-12 using information gathered during the PA/VSI. This form is included in Attachment A. The VSI is summarized and five inspection photographs are included in Attachment B. Field notes from the VSI are included in Attachment C.

2.0 FACILITY DESCRIPTION

This section describes the facility's location; past and present operations; waste generating processes and waste management practices; history of documented releases; regulatory history; environmental setting; and receptors.

2.1 FACILITY LOCATION

The MFRC facility is located at 4025 South Princeton Avenue in Chicago, Cook County, Illinois. Figure 1 shows the location of the facility in relation to the surrounding topographic features (latitude 41°49'01" N and longitude 87°38'00" W).

The facility is bordered on the north and east by Chicago International/Chicago Inc.; on the west by Jernberg Forging Company; and on the south by a residential area.


2.2 FACILITY OPERATIONS

MFRC, a wholly-owned subsidiary of Heatbath Corporation, is a chemical blending operation that manufactures products used by the metal finishing industry during heat treating and metal finishing operations. Wastewater streams are generated when the acidic liquid blending tanks and alkaline powder blending tanks are washed and when wastewater from the wet scrubbers in the powder blending area are drained. Wastewater is treated in the Wastewater Treatment System (SWMU 1).

Raw materials used to manufacture finished goods include various salts, acids, and alkalis. Raw materials are stored in 50-to 100-pound bags and in 55-gallon steel and plastic drums. These bags and drums are stored in a warehouse that adjoins the production area. Sulfuric, nitric, phosphoric, and hydrochloric acids are stored in aboveground storage tanks. Finished products are stored in the warehouse in 55-gallon steel and plastic drums, in other drums of various sizes, or in returnable 360-gallon tote bins.

The facility has manufactured metal finishing and heat treating proprietary products since its construction in 1962. The facility employs 13 people. In the past, alkaline powders and cyanide salts were blended at the facility. This line of products was discontinued in May 1992. The facility treated rinse water contaminated with cyanide through August 1992.

The facility is comprised of two buildings each approximately 26,000 square feet. The building to the north, the production building, was constructed in 1962. The eastern half of this



building is used to store finished products and raw materials. The liquid blending room, powder blending room, and the wastewater treatment area are located in the western half of the production building. The Hazardous Waste Storage Area (SWMU 2) is in the southeastern part of the building and is approximately 10 feet by 35 feet. A corridor connects the production facility to a warehouse of approximately 26,000 square feet. The warehouse, built in 1989, stores raw materials and finished goods. The land underlying the warehouse was leased by MFRC to an adjacent business.

2.3 WASTE GENERATION AND MANAGEMENT

Wastes are generated and managed at various locations at the facility. The facility's SWMUs are identified in Table 1. The facility layout, including SWMUs, is shown in Figure 2. The facility's waste streams are summarized in Table 2.


The waste streams generated at the facility include nonhazardous rinse water and WWTS sludge (D007). Rinse water may contain chromium, depending on the product MFRC is blending. Rinse waters are generated when chemical blending tanks in the liquid acid blending room and powder blending room are washed and when the wet scrubbers in the powder blending room are drained. Wastewater treatment sludge (D007) is generated during the treatment of rinse water.

An average of 19,300 gallons of rinse water is treated per month. Rinse waters are gravity fed through a floor drainage system to the WWTS (SWMU 1). Treatment consists of pH neutralization and metal hydroxide precipitation. This treatment generates WWTS sludge (D007). The sludge is filtered, dried, and placed in a 55-gallon steel drum at the point of generation. When full, the drum is transferred to the Hazardous Waste Storage Area (SWMU 2), and the sludge is emptied into a 1-cubic-yard Chemical Waste Management chemical (chem) pack. The average volume of sludge generated is three 1-cubic-yard chem packs per month. Van Waters and Rogers, Inc. (VW&R), transports the sludge to the Laidlaw Environmental Services, Inc. (Laidlaw), hazardous waste landfill in Pinewood, South Carolina. The filtrate, approximately 19,100 gallons per month, is discharged to Metropolitan Water Reclamation District of Greater Chicago (MWRDGC).

The facility formerly blended alkaline powders and cyanide salts. Rinse water, generated when the blending tanks were washed out, underwent cyanide destruction, pH neutralization, and heavy metal precipitation. The resulting WWTS sludge (D007) was placed in 55-gallon steel

TABLE 1
SOLID WASTE MANAGEMENT UNITS

SWMU Number	SWMU Name	RCRA Hazardous Waste <u>Management Unit</u> ^a	Status
1	Wastewater Treatment System (WWTS)	No	Active; less than 90-day storage and treatment of hazardous waste
2	Hazardous Waste Storage Area	Yes	Active; greater than 90-day storage of hazardous waste
Note:	<u>. </u>	•	
	RCRA hazardous waste mana quired submittal of a RCRA I		



LEGEND

SWMU 1

WASTEWATER TREATMENT SYSTEM HAZARDOUS WASTE STORAGE AREA SEWER DRAINS TO WASTEWATER TREATMENT SYSTEM

NOT TO SCALE

METAL FINISHING RESEARCH CORPORATION CHICAGO, ILLINOIS

FIGURE 2 FACILITY LAYOUT

FIRE ENVIRONMENTAL MANAGEMENT, INC.

SOURCE: MODIFIED FROM MFRC SKETCH RECEIVED BY PRC ON JANUARY 14, 1993

TABLE 2 SOLID WASTES

Waste/EPA Waste Code ^a	Source	Solid Waste <u>Management Unit</u>
Rinse water/NA	Powder and liquid blending tank washdowns, wet scrubber drainage	SWMU 1
WWTS Sludge/D007	Rinse water treatment	SWMU 2
Note:	, ,	
a Not applicable (NA) designate	es nonhazardous waste.	•

drums at the point of generation and transferred to the Hazardous Waste Storage Area (SWMU 2) for storage. In May 1992, the facility discontinued manufacturing cyanide salt-formulated products. Until August 1992, MFRC continued to treat powder room rinse water to destroy residual cyanide remaining in the system. The resulting WWTS sludge (D007) was placed in 55-gallon steel drums and transferred to the Hazardous Waste Storage Area (SWMU 2) for storage.

2.4 HISTORY OF DOCUMENTED RELEASES

The facility has no history of documented releases.

2.5 REGULATORY HISTORY

On August 4, 1980, MFRC submitted a Notification of Hazardous Waste Activity form to EPA (MFRC, 1980a). On November 17, 1980, MFRC submitted a RCRA Part A permit application. The Part A permit application included a container storage area with a capacity of 55 gallons per day; referring to the Hazardous Waste Storage Area (SWMU 2). The following waste codes were listed on the Part A permit application: sodium cyanide (P106), ignitables (D001), corrosive wastewater (D002), chromium (D007), and barium (D005) (MFRC, 1980b).

There is no documentation in IEPA, EPA, or facility files that ignitable waste (D001) was ever generated or managed at the facility. Facility representatives stated that corrosive wastewater (D002) was filed protectively. Rinse waters and sludges have never been analyzed for barium (D005) and manifests indicate that all WWTS sludge has been assigned the D007 waste code. There is no documentation concerning the disposal of sodium cyanide or containers with sodium cyanide residue (P106).

IEPA inspected the facility on three occasions between 1982 and 1989 (IEPA, 1982; 1986; 1989a). These inspections revealed violations concerning waste analysis plans, personnel training plans, closure and post-closure plans, and other paperwork. All violations and notices of noncompliance have been resolved and are noted in IEPA files (IEPA, 1991).

The facility is currently regulated as a generator of hazardous waste and a treatment, storage, or disposal (TSD) facility. Manifests indicate that hazardous waste (D007) has been stored for greater than 90 days. On November 8, 1992, the facility's interim status was revoked by IEPA (IEPA, 1989b), thus requiring MFRC to initiate closure of the Hazardous Waste Storage Area (SWMU 2).

On August 19, 1991 MFRC submitted a closure plan for the Hazardous Waste Storage Area (SWMU 2). The plan was not approved for various paperwork deficiencies. MFRC is currently addressing the deficiencies and preparing a new plan.

RCRA files reveal contradicting letters by IEPA personnel on whether MFRC should be regulated as a generator only or a TSD facility. On September 28, 1988, MFRC submitted a Part A permit application withdrawal request, asking that the facility's status be changed from a TSD to a generator (MFRC, 1988). This request was denied because manifests indicated that waste shipments occurred more than 90 days after the previous shipment was sent off site; therefore, until MFRC closes the RCRA-regulated Hazardous Waste Storage Area (SWMU 2), the facility will remain regulated as a TSD (EPA, 1993).

MFRC is not required to have air permits. MFRC discharges filtrate from the WWTS (SWMU 1) directly to a combined sewer of the MWRDGC. There is no permit required for this release.

The facility has never used underground storage tanks. PRC did not observe any documents indicating CERCLA activity at the facility.

2.6 ENVIRONMENTAL SETTING

This section describes the climate; flood plain and surface water; geology and soils; and ground water in the vicinity of the facility.

2.6.1 Climate

The climate in Cook County is continental, with cold winters and warm summers. The average daily temperature is 49 degrees Fahrenheit (°F). The lowest average daily temperature is 21.1 °F in January. The highest average daily temperature is 83.6 °F in July (Gale, 1978).

The total annual precipitation for the county is 35.12 inches (NOAA, 1991). The median annual precipitation for the county is 34 inches (NOAA, 1991; USDC, 1968). The mean annual lake evaporation is 29.5 inches (USDC, 1968). The average snowfall from November to April is 37 inches. The 1-year, 24-hour maximum rainfall recorded in the area is 6.24 inches (Gale, 1978).

The prevailing wind is from the west-southwest. Average wind speed in highest in March at 11.8 miles per hour from the west (USDC, 1968).

2.6.2 Flood Plain and Surface Water

MFRC is not located in a 100-year flood plain (FEMA, 1992). The topography in the vicinity of the site exhibits low relief with a gentle slope to the southeast. The nearest bodies of water are the South Fork of the Chicago River, which lies 1.3 miles to the northwest of the facility and Lake Michigan which lies 2 miles to the east of the facility. The South Fork is used for industrial purposes and leads to the Chicago Sanitary and Ship Canal, which flows southwestward and is also used for industrial purposes (USGS, 1980).

Natural drainage in the vicinity of the facility has been altered by roadways, structures, and other features. Surface water runoff from the facility flows into storm sewers, which are located at each side of the loading docks on the east side of the facility. These sewers discharge to the Chicago Sanitary and Ship Canal through the combined sanitary and MWRDGC sewer. Permits are not required for storm water runoff discharge to the combined sewer system.

2.6.3 Geology and Soils

Facility-specific geology information was not available; therefore, regional information is presented. The MFRC facility is located on Lake Plain deposits from glacial Lake Chicago (present Lake Michigan). The Lake Plain deposits are a member of the Wadsworth Till of the Wedron Formation of the Pleistocene Epoch. The Wadsworth Till was deposited during the Wisconsinan glacial stage between approximately 12,500 and 22,000 radiocarbon years before present (BP) (ISGS, 1971).

The Wadsworth Till is a gray till interbedded with sorted sediments and composed primarily of sheet-like deposits of silt and clay-sized products separated by beds of sand and gravel. The thickness of the unconsolidated deposits in the vicinity of the facility is approximately 50 feet (ISGS, 1971).

The unconsolidated sediments in the region unconformably overlie Silurian-age bedrock. The uppermost bedrock unit is dolomite or dolomitic limestone of the Niagarian and Alexandrian Formation. The Silurian-age formations were typically formed as reef deposits built while Illinois lay under a shallow sea between 400 and 435 million years BP. The thickness of the Silurian-age formation in the vicinity of the facility is approximately 200 to 250 feet (ISGS, 1971).

In the vicinity of the facility, underlying the Silurian bedrock units is the 200-foot-thick Maquoketa Shale Group, deposited during the Ordovician period. The Maquoketa Shale Group is composed of several individual shale formations and a limestone formation deposited approximately 435 to 600 million years BP (ISGS, 1971).

The older Ordovician and Cambrian bedrock units beneath the Maquoketa Shale Group are composed primarily of limestone and sandstone and are typically in excess of 2,000 feet thick (ISGS, 1971).

2.6.4 Ground Water

The till layer of the Wadsworth Till generally does not provide sufficient yields to be utilized as a drinking water source because of its low permeability. The localized interbedded sand, silt, and gravel deposits can yield moderate quantities of ground water. Recharge to the till and associated localized sand, silt, and gravel units typically occurs locally from precipitation (ISGS, 1955).

The bedrock unit below the unconsolidated material in northern Illinois is an important aquifer; however, ground water from the aquifer is not used as a drinking water source in Chicago because of the availability of water from Lake Michigan. Ground water in the Niagarian and Alexandrian aquifers ranging from 50 to 400 feet below ground surface (bgs) is primarily obtained from joints, fissures, and solution cavities. The water-bearing openings are irregularly distributed both vertically and horizontally in the units (ISGS, 1955).

Beneath the confining Maquoketa Shale Group are high yielding Ordovician- and Cambrian-age Galesville, Mt. Simon Sandstone, and Eau Claire and Franconia Formations. These units are frequently used aquifers in northeastern Illinois. The Galesville sandstone ranges in depth from 1000- to 1800-feet in Cook County and at one time most municipal and major industrial water supplies were obtained from this aquifer (ISGS 1955).

2.7 RECEPTORS

MFRC occupies 1.2 acres in an industrial and residential area in Chicago, Cook County, Illinois. Chicago has a population of about 3 million people. MFRC employs 13 people. The facility is bordered on the north and east by Chicago International/Chicago, Inc.; on the west by Jernberg Forging Company; and on the south by several single family residences.

The nearest residential area is located about 0.1 mile south of the facility. The facility is equipped with double-locked door entrances and a 24-hour security alarm system.

The nearest surface water body, the South Fork Chicago River, is located 1.3 miles northwest of the facility and is used for industrial purposes. Other surface water bodies in the area include Lake Michigan, 1.8 miles east; ponds in Sherman Park 2.0 miles southwest, Washington Park, 2.2 miles southwest; and McKinley Park, 2.4 miles west-northwest of the facility.

Ground water is not used as a drinking water source in Chicago because of the availability of water from Lake Michigan.

Sensitive environments are not located on site. The nearest sensitive environment, a wetland, is located 2.0 miles southwest. This area is an excavated open water area located in Sherman Park.

3.0 SOLID WASTE MANAGEMENT UNITS

This section describes the two SWMUs identified during the PA/VSI. The following information is presented for each SWMU: description of the unit, dates of operation, wastes managed, release controls, history of documented releases, and PRC's observations. Figure 2 shows the SWMU locations.

SWMU 1

Wastewater Treatment System

Unit Description:

The WWTS consists of a sewer system with a drain in the acid liquid blending room and the powder blending room. This sewer system vents to two holding tanks in the wastewater treatment area. The wastewater treatment area is approximately 30-by 60-feet. The WWTS consists of two approximately 900-gallon holding tanks, two approximately 1,100-gallon treatment tanks, one 2,600-gallon settling tank, and one filter press. The holding and treatment tanks are constructed of lined concrete and are inground. The system treats an average of 19,300 gallons of rinse water per month. A 55-gallon drum is filled with dried hazardous waste sludge (D007), which is a product of the WWTS.

Date of Startup:

The unit began operation in 1973. Wastewater treatment practices by the facility from 1962 to 1973 are unknown.

Date of Closure:

This unit is active.

Wastes Managed:

This unit manages nonhazardous drainage rinse water generated when acidic liquid blending tanks and alkaline powder blending tanks are washed and when powder room wet scrubbers are drained. MFRC treats the rinse water in batches, generating WWTS sludge.

This unit formerly managed nonhazardous rinse water generated by manufacturing powdered products formulated with cyanide salts. Rinse water from the powder blending room was treated to destroy cyanide using sodium hypochlorite. In May 1992, MFRC discontinued manufacturing cyanide salt-containing products. Until

August 1992, MFRC continued to treat powder room rinse water for cyanide to destroy residuals that may have been in the system.

Release Controls:

This unit's drainage system has a corrosive-resistant tile lining. Holding and treatment tanks are constructed of lined concrete without secondary containment. Floor drains direct spills to the WWTS. All concrete is epoxy-sealed. The unit is located indoors and is equipped with high-level alarms.

History of Documented Releases:

There is no history of documented releases from this unit.

Observations:

During the VSI, the unit was treating rinse water. PRC observed a 4-foot-radius stained area around the drain in the acid liquid blending room; however, the concrete was not pitted or cracked. PRC observed that the area around the drain in the powder blending room was stained; however, the concrete was not pitted or cracked. No evidence of spills or overflows was observed around the holding and treatment tanks (see Photographs No. 1, 2, 3, and 4).

SWMU 2

Hazardous Waste Storage Area

Unit Description:

The Hazardous Waste Storage Area is an indoor, 10-foot by 35-foot, epoxy-sealed concrete pad located in the southeastern quarter of the production facility. Yellow paint clearly marks its boundaries and "Hazardous Waste Storage Area" is clearly printed in the yellow paint. There are no floor drains in this unit. The nearest floor drain is 50 feet away. This drain leads to the WWTS.

Date of Startup:

This unit began operation about 1973. Storage practices of the facility from 1962 to 1973 are unknown.

Date of Closure:

This unit is active.

Wastes Managed:

This unit manages hazardous dried WWTS sludge (D007) generated by the WWTS (SWMU 1). The sludge is stored in 1-cubic-yard chem packs until it is picked up for disposal by Van Waters and

Rogers and landfilled in Laidlaw's South Carolina Pinewood Hazardous Waste landfill.

Release Controls:

This unit is an epoxy-sealed concrete pad located indoors. It manages dried WWTS sludge (D007). There are no berms, dikes, or drains in the area.

History of Documented Release:

No releases from this unit have been documented.

Observations:

During the VSI, the unit contained one full steel-strapped chem pack and one partially full chem pack (see Photograph No. 5).

4.0 AREAS OF CONCERN

PRC identified no AOCs during the PA/VSI.

5.0 CONCLUSIONS AND RECOMMENDATIONS

The PA/VSI identified two SWMUs and no AOCs at the MFRC facility. Background information on the facility's location; operations; waste generating processes and waste management practices; history of documented releases; regulatory history; environmental setting; and receptors is presented in Section 2.0. SWMU-specific information, such as the unit's description, dates of operation, wastes managed, release controls, history of documented releases, and observed condition, is presented in Section 3.0. Following are PRC's conclusions and recommendations for each SWMU. Table 3, located at the end of this section, summarizes the SWMUs at the facility and the recommended further actions.

SWMU 1

Wastewater Treatment System

Conclusions:

The WWTS consists of a sewer system with a drain in the acid liquid blending room and the powder blending room. This sewer system vents to two holding tanks in the wastewater treatment area. The WWTS consists of two holding tanks, two treatment tanks, one settling tank, and one filter press. A 55-gallon drum is filled with dried hazardous WWTS sludge (D007), which is generated by the WWTS. The potential for release to environmental media is summarized below.

The potential for release to ground water, surface water, air, and on-site soils is low. Spills and leaks are contained in the WWTS sewer which is constructed of corrosive-resistant tile. Tanks are lined concrete and all concrete floors are epoxy sealed. The nearest surface water is 1.3 miles northwest of the facility. Particulates and airborne dust in the powder blending room are exhausted and directed to wet scrubbers. The facility does not use any solvents or products containing VOCs during its operation.

Recommendations:


PRC recommends no further action for this SWMU at this time.

SWMU 2

Hazardous Waste Storage Area

Conclusions:

The Hazardous Waste Storage Area is located indoors on a 10-foot by 35-foot epoxy sealed concrete pad. Dried hazardous waste sludge (D007), generated by the WWTS, is stored in 1-cubic-yard chem packs before being transported by Van Waters and Rogers to Laidlaw's South Carolina



Pinewood Hazardous Waste landfill. The potential for release to environmental media is summarized below.

The potential for release to ground water, surface water, air, and on site soils is low. The waste is dried sludge and resistant to flow. The unit is located indoors on an epoxy-sealed concrete floor. The dried sludge contains no solvents or VOCs. The facility is located in an urbanized area that is almost entirely paved.

Recommendations:

PRC recommends no further action for this SWMU at this time.

ENFORCEMENT CONFIDENTIAL

TABLE 3 SWMU SUMMARY

	SWMU	Dates of Operation	Evidence of Release	Recommended Further Action
1.	WWTS	1973 to present	None	No further action
2.	Hazardous Waste Storage Area	1973 to present	None	No further action

REFERENCES

- Federal Emergency Management Agency (FEMA), 1992. Flood Insurance Rate Maps, Special Flood Hazard Areas.
- Gale Research Company (Gale), 1978. Climates of the United States, Alabama Montana, Volume 1.
- Illinois Environmental Protection Agency (IEPA), 1982. Observation Report by Charles Gebien, IEPA/EPS, August 23.
- IEPA, 1986. RCRA Inspection Report by Richard Finley IEPA/EPA, October 22.
- IEPA, 1989a. IEPA Inspection Report by Mary Glynn, IEPA/EPA, July 27.
- IEPA, 1989b. IEPA Letter to MFRC, June 20.
- IEPA, 1991. IEPA Letter to Division file, June 10.
- IEPA, 1991b. Notice of Disapproval of Closure Plan, August 19.
- Illinois State Geological Survey (ISGS), 1955. Groundwater Possibilities in Northeastern Illinois, Circular 198.
- ISGS, 1971. Summary of the Geology of the Chicago Area.
- Metal Finishing Research Company (MFRC), 1980a. Notification of Hazardous Waste Activity Form, U.S. EPA Form 8700-IL, August 4.
- MFRC, 1980b. Hazardous Waste Permit Application, U.S. EPA Form 3510-3, November 17.
- MFRC, 1988. Facility Part A permit application Withdrawal Request Form, September 28.
- National Oceanic and Atmospheric Administration (NOAA), 1991. Local Climatological Data: Annual Summary with Comparative Data for Chicago, O'Hare International Airport.
- U.S. Department of Commerce (USDC), 1968. Climatic Atlas of the United Sates, U.S. Government Printing Office.
- U.S. Environmental Protection Agency (EPA), 1993. Letter from George Hamper, EPA to Francene Harris, EPA, January 4.
- U.S. Geological Survey (USGS), 1980. 7.5-Minute Topographic Series: Modified Englewood and Jackson Park Quadrangles, Illinois.

ATTACHMENT A EPA PRELIMINARY ASSESSMENT FORM 2070-12



POTENTIAL HAZARDOUS WASTE SITE PRELIMINARY ASSESSMENT PART 1 - SITE INFORMATION AND ASSESSMENT

I. IDENTIFICATION								
01 STATE	02 SITE NUMBER							
π	II JD 045 700 945							

II. SITE NAME AND LOCATION						
		T				
01 SITE NAME (Legal, common, or descriptive name of site) Metal Finishing Research Corporation	1	· ·	T, ROUTE NO. OF outh Princeton		IION IDENTIFIER	·
03 CITY Chicago		04 STATE	05 ZIP CODE 60609	06 COUNTY Cook	07 COUNTY CODE	08 CONG DIST
	ONGITUDE 7°38'00" W					
10 DIRECTIONS TO SITE (Starting from nearest public re From Pershing Road, turn south onto Princeto		cility is loca	ated two blocks	s south of the	Princeton and	Pershing Intersection.
III. RESPONSIBLE PARTIES						-
01 OWNER (if known) Metal Finishing Research Corporation			T (Business, mailing) outh Princeton	-		
03 CITY Chicago		04 STATE	05 ZIP CODE 60609	06 TELEPHONE (312) 373-080		
07 OPERATOR (If known and different from owner)		08 STREE	T (Business, meilii	ng, residential)		
O9 CITY	· **** ***	10 STATE	11 ZIP CODE	12 TELEPHONE	NUMBER	
13 TYPE OF OWNERSHIP (Check one) ■ A. PRIVATE □ B. FEDERAL: (Agency	Alemei	□ C. STA	TE D.	COUNTY	E. MUNICIPA	AL ·
☐ F. OTHER (Specify)	——————————————————————————————————————	□ G. UNK	NOWN			
14. OWNER/OPERATOR NOTIFICATION ON FILE (Check all B. A. RCRA 3010 DATE RECEIVED: 8 /4 /80 MONTH DAY YEAR	that apply) B. UNCONTROLLE	D WASTE SIT	TE (CERCLA 103 d	:/ DATE RECEIVI	ED: / /	C. NONE
IV. CHARACTERIZATION OF POTENTIAL HAZAF	rD					
01 ON SITE INSPECTION BY (Check ell to	hat apply) ■ B. EPA CO	NTRACTOR	C. STATE	_ D	. OTHER CONTRA	ACTOR
□ NO	E. LOCAL HEALTH OF NAME(S): PRC Env			(Spec	cify)	
02 SITE STATUS (Check one)		EARS OF OP		me. (I Re)		
■ A. ACTIVE □ B. INACTIVE □ C.UNKNO		1962			□ UNKNO	wn
04 DESCRIPTION OF SUBSTANCES POSSIBLY PRESENT, KI Substances related to the manufacture of chemical bl and products containing chromium.			···		shing industry, i	ncluding acids, alkalies
05 DESCRIPTION OF POTENTIAL HAZARD TO ENVIRONMENT Residue on floor in the chemical blending room		N				
V. PRIORITY ASSESSMENT		·				
01 PRIORITY FOR INSPECTION (Check one. If high ar media	um is checked, complete	Part 2 - Was	te Information and	d Part 3 - Descript	ion of Hazardous	Conditions and Incidents.)
□ A. HIGH □ B. MEDIUM (Inspection required promptly) (Inspection required)	■ C. LOW (Inspect on tim	o availablo ba:	□ D. NONE sis) (No further	action needed; c	omplete current d	isposition form)
VI. INFORMATION AVAILABLE FROM			· · · · · · · · · · · · · · · · · · ·			
01 CONTACT Kevin Pierard	02 OF (Agency/Organi U.S. EPA	zation)				03 TELEPHONE NUMBER (312) 886-4448
04 PERSON RESPONSIBLE FOR ASSESSMENT Michael Duffin	05 AGENCY	06 ORG	SANIZATION	07 TELEPHON (414) 821-58		08 DATE 02 / 04 / 93 MONTH DAY YEAR
EPA FORM 2070-12(17-81)		L		L .	<u></u>	MONTH DAT TEAM

ATTACHMENT B
VISUAL SITE INSPECTION SUMMARY AND PHOTOGRAPHS

VISUAL SITE INSPECTION SUMMARY

Metal Finishing Research Corporation 4025 South Princeton Avenue Chicago, Illinois 60609 ILD 045 700 945

Date:

January 14, 1993

Primary Facility Representative:

Williams W. Walen, Vice President, Metal Finishing

Research Corporation (MFRC)

Representative Telephone No.:

(312) 373-0800

Inspection Team:

Michael G. Duffin, PRC Environmental Management, Inc.

(PRC)

Scott Storlid, PRC

Photographer:

Scott Storlid, PRC

Weather Conditions:

Clear, calm; 15 °F, 4 to 6 inches of snow on the ground

Summary of Activities:

The visual site inspection (VSI) began at 9:52 a.m. with an introductory meeting. The inspection team explained the purpose of the VSI and the agenda for the visit. Facility representatives then discussed the facility's past and current operations, solid wastes generated, and release history. Facility representatives provided the inspection team with copies of requested documents.

The VSI tour began at 10:46 a.m. The entire facility was inspected. Raw material and finished good storage areas were checked for leaking containers. None were observed. Liquid blending rooms and powder blending rooms were inspected and the Wastewater Treatment System (SWMU 1) was identified. Stains were observed around the drains in the chemical blending rooms. The Hazardous Waste Storage Area (SWMU 2) was identified and inspected. No sign of leakage was observed. Finally, the laboratory and the wastewater treatment areas were inspected. The construction and processes of the treatment unit were observed.

The tour concluded at 11:15 a.m., after which the inspection team held an exit meeting with facility representatives. The VSI was completed and the inspection team left the facility at 11:29 a.m.




Photograph No. 1 Orientation: Southwest

Description:

. 1 Southwest Date: 01/14/93
This photograph shows the wastewater pipe leading to the drain in the liquid

chemical blending room. The dark circle around the drain is from wastewater




Photograph No. 2
Orientation: Southwest
Description: This photog

This photograph shows the wastewater pipe leading to the drain in the powder blending room. The floor stains are from wastewater drainage. The drain is beneath the metal roll conveyor.

Location: SWMU 1


Date: 01/14/93




Photograph No. 3 Orientation: South

This photograph shows the top of the belowground treatment tanks in the wastewater treatment area. The tanks are located below the metal diamond plates. Description:

Date: 01/14/93



Southwest Date: 01/14/93
This photograph shows the filter press and the dried sludge being placed in a 55gallon steel drum at the point of generation. Photograph No. 4 Orientation: Sou Description:



Photograph No. 5 Orientation: East Description: This photog

East Date: 01/14/93
This photograph shows the Hazardous Waste Storage Area (SWMU 2). Not shown in the picture are one full chem pack and one partially full chem pack being managed in the area.

ATTACHMENT C VISUAL SITE INSPECTION FIELD NOTES

ŧ

) 1/19193	10.3
HEATBATH - PARIK	FINISHING AND HEAT
METALLURGICAL CORPORATION	TREATING INKUSTRIES.
METAL FINISHING RESEARCH	LIVOIL AND LIQUID -
CLEAR, CALM, 15°F	PROBUCTS
	- RAN MATERIALS -
2952 ARRIVE ON SITE	SALTS, OXINES,
MEET WILLIAMS W.	CU SULFATE ACIDS,
MEET WI WILLIAMS W.	ALKAZINES
BEGIN USI MEETING	- STORED N BAGS
	ABOUT GROUND TANKS,
- MARUFACTURING FACILITY	55-CALLON BRUMS
26,000 pt ? - EARLY 60'S	ABT- 4 TOTAL
- WAREHOUSE 26,000 PJZ-	- PRODUCTION
2 1989	1) 21QUID BLENDING-
- WAS AN EMPTY LOT -	TANKS PROBUCT
FOR PARKING	DIRECTLY TO 55-6AL.
- 13 Emproyees -	brums or TOTES.
- BLEND PROPERTARY	TANK WASHING-
PROBUCTS FOR METAL	WASTE PIACE DIRECTLY

10.1 TO WTO - WINE ARRAY	ى , ى ج
OF PRODUCT SÓ UNSURE	TO SETTLING TANK,
IF WASTEWATER 15	THEN FILTERED-
HAZ -HAVENT AMALYZES	EFFLUENT RELEASED
THEM.	msb=
WTS - SINCE MID 60'S	-SLUNGE- COLLETED
- TREATING WISC -	AT AT THE FILTCE-
SARGETY OF WASTE	AMOUNT VARCES - A
DEPLACENT ON	2 Brums/wk.
PRODUCTION	5007
- CHROME RENUCTION,	· VAN WATERS + ROCERS
NOTERLIZATION,	LANDFILLED Q HAZ.
PH ADJUST, FLOC.	WASTE LANDFILL
-15 2 SYSTEMS-	PINEWOOD SC.
1 FOR LIQUID 1 FOR	-NO PERMIT FOR EFFLUEN
POWER-	RELEASE W/ msb-
Eq. 495 1 HOLDING	compliance ul carcolor
TANK, FURPER TO	STANBARBS
TREATMENT TANK	- HW STORAGE ARCA-
TREATED, DUMPEN	portans mist sood

10	1		<u> </u>	 		· · · · · · · · · · · · · · · · · · ·				101
-	70	BC	48m.	PAK		FROD	JUCY -	SMAL	- Am	00 NT
	-			· ! 		+ OCCA	51027	rx c	LEAN	
	2) 10	NNO	1 23	PROCE	55	DEN	~5 -	~~A	TER 7	٥
	- DV	ST . E)	HAUS	TESFER	0m	WY	h			
	W	13 CHIN	23	THRO	V6H	- FLO	\$ 570	SRAIN	5 12	1
	6	WET	SCRU	BISER	-			LITT		ļ
	MA	(b)	0 2	73				7 W		
•	1 .	ASTEC)		>4
		UPSH1	1	ì		•	ľ	110		
		WTS						1	1	{
			~~	- D.F.A.		WT		BAIN		
	6	NR C	roalid	S IN DO	1518C 0 5 -				- ^ 0	
		W DI		1	1 .	- HW:		1.	HICC	D
	1	1					196			
		SOPOC					T	1. 15		
		50P0					1	56		١.
<u>·</u>	- 5	10PC4		10000	- W/	WA3	ERIAL	5 +	F1413	HEN
<u>. </u>	_	ABOV					1	12 15		
	ac-L	AB				CUR	RENT	Y F	DR 51	42E.
	<u> </u>	ERAT 1	2 v	FOF	FSIEC	Emp.	14 F	RUMS	5701	26b
		1		1						

د	347	26- N	0 14.0	1.570	ta 62,						109
	TO 1	41519	Mon	EDGE,	<u> </u>		Dun	1813	NTO	PAIC	>
	74	حصو ماه	en .	JAS.		·	3HW	N 121	LL		
						· · · · · · · · · · · · · · · · · · ·	100	to			
	محرد	SON	BYTTA	SEN	8	1055	PIC	1 ε	AST	- HN	SA
		OFF.	j		ļ.						.·
	}	200		,			RAW	MAT	ER(AL	STORA	LE
	_	TIF								3266.	
	1	1990	i	ľ	1			:			
		ECULF	'				WET	R001-	- 5	ANKS	
										LOOR	
046	RECI	N 15	¥ τλ	UR		·	_	r b			
	ł	60435		1			WY				
		005		1 -							
1051		,		I .	BLDG.	1059	bic 3	_S W	- NR	Ain	
1001		STORAC		!	5-4-		1	i .	1	ans 1	>11.8
		354	1	1				r, che	1		
	1	75CC	ł	ļ	158 /		1.15	11020	0 1915		
	i	1	_	1	170.15	1102	b (3	<i>c</i> (.	1 . 101	of CD	1)
		CHE				1102]			T
	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	DKU	w 4	0 132	<u> </u>		<u> </u>	7 5	CRUB	BC15	BRA,
	1	ļ	!						 		

) \ '		· 	-	ļ		1115	52L V	ST - W	SPAP U	> M55+	11
	TOP	OWER	(DREY)	SILE	345 Y		!			STOR	
	WT	5 136	NEAT	H ROI	LER.		FOR	GRE	ATER	THAN	
							90-	2 YAd	- 17	AUE	
165	المع و	ER V	445			<u>. </u>	STO	کزی	FOR	GREA	TER
							THA	7 9	0-NA	15 BC	FOR(
1107	Y SAS	PIC 4	50	17H	TIMED .	· 	1987	9			
		22012	6 4	15 71	LEATMENT		+05	SIBLE	THAT	-	
	TA	025	BELO	W PI	ATE		C.Y.	4 O-	5A45	WAS	
		TOF					JUST-	CSHIP	servicen SENT	<u>5</u> -	
mes	BLSET	TLIN	6 71	ANK	SUDEA			THE		İ	
							514001	-b 15	GIN	WHEN	
1109	PIC	5	5 W.	FIL	TER		700	344	A FUL	- BRUM	۸
	PR	55	4 Da	307	SRUM		PLAN	00	RCRA	1126	
	OF	WY	-5					14~			
							SUR	ب س	+ 5 2 +	·	
	WYS	- SEP	LED	CONC	RETF	1124					٤
	1	FLOO						L177			
	FFF	LUEN		0,33	UGAL						
	\		192.					\ \X	() X	de	
			·						, CA		
			6 (CE)	24 25 B 25 E	1042624						